

2011-02-24 Thursday Morning Notes


Thursday, February 24, 2011

9:17 AM

Interesting Happenings

- Pbar Dry Engine failure on the early owl shift.
- Dry Engine expander overhaul required.


Plots



```

PC P36 STOCHASTIC PARAM'S
P36 Cryo Preamps (All Bands) SET D/A A/D Com-U *PTools*
-<FTP>*SA* X-A/D X=TIME Y=I:VP321 ,I:VP521 ,
COMMAND BL-- Eng-U I= 0 I=-4 , -3 , -10 , -10
-< 3>* s_MI AUTO F= 1 F= 6 , 7 , 10 , 10
stack_t_mo stack_t_be core_m.&.b DEBUN_COOL misc_hrdwr lab-4
! Upstream Cryo Amp Permit if Temps < 40K
D:CRYO05 Cryo Amp Interlock Trip T
D:P1TRT5 TANK #D601 TEMP 54.62 DECK
D:P1TRT6 TANK #D602 TEMP 60.16 DECK
D:P1TRT7 TANK #D603 TEMP 61.46 DECK
D:H1AU1 Deb Horz Band 1 Up Amp *T
D:H1AL1 Deb Horz Band 1 Lo Amp *T
D:V1AU1 Deb Vert Band 1 Up Amp *T
D:V1AL1 Deb Vert Band 1 Lo Amp *T
D:H2AU1 Deb Hor Band 2 Upper Amp *T
D:H2AL1 Deb Hor Band 2 Lower Amp *T
D:V2AU1 Deb Vert Band 2 Up Amp *T
D:V2AL1 Deb Vert Band 2 Lo Amp *T
D:PH1AU1 Deb Mon/Hor Bnd 1 U Amp *T
D:PH1AL1 Deb Mon/Hor Bnd 1 L Amp *T
D:PV1AU1 Deb Mon/Ver Bnd 1 U Amp *T
D:PV1AL1 Deb Mon/Ver Bnd 1 L Amp *T
D:PH2AU1 Deb Mon/Hor Bnd 2 U Amp *T
D:PH2AL1 Deb Mon/Hor Bnd 2 L Amp *T
D:PV2AU1 Deb Mon/Ver Bnd 2 U Amp *T
D:PV2AL1 Deb Mon/Ver Bnd 2 L Amp *T
! Downstream Cryo Amp Permits if Temps < 40K
D:CRYO05 Cryo Amp Interlock Trip T
D:P1TRT1 TANK #D106 TEMP 49 DECK
D:P1TRT2 TANK #D105 TEMP 49.55 DECK
D:P1TRT3 TANK #D104 TEMP 50.98 DECK
D:H3AU1 Deb Horz Band 3 Up Amp *T
D:H3AL1 Deb Horz Band 3 Lo Amp *T
D:V3AU1 Deb Vert Band 3 Up Amp *T
D:V3AL1 Deb Vert Band 3 Lo Amp *T
D:H4AU1 Deb Hor Band 4 Up Amp *T
D:H4AL1 Deb Hor Band 4 Lo Amp *T
D:V4AU1 Deb Vert Band 4 Up Amp *T
D:V4AL1 Deb Vert Band 4 Lo Amp *T
D:PH3AU1 Deb Mon/Hor Bnd 3 U Amp *T
D:PH3AL1 Deb Mon/Hor Bnd 3 L Amp *T
D:PV3AU1 Deb Mon/Ver Bnd 3 U Amp *T
D:PV3AL1 Deb Mon/Ver Bnd 3 L Amp *T
D:PH4AU1 Deb Mon/Hor Bnd 4 U Amp *T
D:PH4AL1 Deb Mon/Hor Bnd 4 L Amp *T
D:PV4AU1 Deb Mon/Ver Bnd 4 U Amp *T
D:PV4AL1 Deb Mon/Ver Bnd 4 L Amp *T

```



Photos

